Date User: Tuesday, 26/05/2009 12:34:02 PM

Julie Dawson

Process Sheet

Customer Job Number **Estimate Number** : CU-DAR001 Dart Helicopters Services

Drawing Name

: 212 BASKET BASE ASS'Y LH

: 48209B : 11542

P.O. Number

This Issue

: 26/05/2009

: NC

: 48202B

S.O. No. :

Part Number Drawing Number : D3053041 : D3053 REVB

Prsht Rev.

: //

: LARGE FAB ASSY Type

Project Number Drawing Revision

Material

Due Date

: B : 01/06/2009

Qty:

1 Um: Each

Checked & Approved By

Comment

First Issue

Written By

Previous Run

: Est. C

02.09.04

M304EX0.75-16F was M750-16FXS-S/S K

J/RF

Est Rev:D 08-08-29 revB as per dwg DD verified by:EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

M304TS0750W065

304 SQ Tube .75x.75x.065V



Comment: Qty.:

D31661

End Bar Scrap = 1.5 sf 45.5000 f(s) 45.5000 f(s)/Unit Total:

304 SQ Tube.75x.75x.065W

1-Cut Rib from 3/4" x 3/4" x 0.065 wall 304/316 SS tubing.

Batch: <u>M111</u>432

2-Drill holes in D3053-3 as per dwg D3053

Basket Hoop



Comment: Qty.: 5.0000 Each(s)/Unit Total: 5.0000 Each(s)

Basket Hoop

Cut

3.0

2.0

Comment: LARGE FABRICATION RESOURCE 1

1-Cut 5 D2235-3 FROM D3166-1 using DT8365

2-Drill holes in three D2235-3 ribs as per dwg D3053 using DT8995

	•									
W/O:			WC	RK ORDER CHANC	GES	 				
DATE	STEP	PRO	CEDURE CHANGE By D			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				•						
Part No	:	PAR #:	Fault Cate	jory:	NCR: Y	es N	o DQ /	1 A:	Date:	<u> </u>
		Resolution: Disposition: QA: N/C Closed: Date:								
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (N	CR)			V****	
	STEP	Description of NC			tion B		Verification Section C		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		ın & ate			Chief Eng	QC Inspector
,										į
	*									
·										
	1									


Date: Tuesday, 26/05/2009 12:34:02 PM User: Julie Dawson **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: 212 BASKET BASE ASS'Y LH Job Number: 48209B Part Number: D3053041 Job Number: Seq. #: Machine Or Operation: Description: 4.0 D23273 Spacer Bushing Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Spacer Bushing Pick: **Qty Part Number** Description Batch 144365 2 D2327-3 Bushing 09.05.27 D22323 Basket Hinge 5.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Basket Hinge Pick: Qty Part Number Description Batch <u>B4682</u>2 2 D2232-3 Hinge plate 6.50.60 6.0 D2581 Mounting Bracket Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Mounting Bracket Pick: **Qty Part Number** Description Batch 4608F D2581 Mounting Bracket 09-05-78 7.0 M304EX07516F Expanded Metal Flat SS Comment: Qty.: Total: 50.4000 sf(s) 50.4000 sf(s)/Unit Expanded Metal Flat Stai Pick: milli73(10) Qty Part Number Description 48sq.ft M304EX0.75-16F **Expanded Metal** LARGE FABRICATION RESOURCE 1 LARGE FAB 1 8.0 Comment: LARGE FABRICATION RESOURCE 1 1-Remove all markings from material 2-Weld as per Dwg D3053 using Welding Table and corner Jig Deburr as required ****Ensure ribs are positonned for LH**** PD 09.05.26

W/O:		,	WO	RK ORDER CHANGE	S	- 0 .		***************************************	
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						·			
			•						
Part No		PAR #:	Fault Categ	ory:					
Resolution:			Disposition	:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	1)		· · · · · ·	
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DAIL	Section	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
· · · · · · · · · · · · · · · · · · ·									•


Tuesday, 26/05/2009 12:34:02 PM Date: User: Julie Dawson **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: 212 BASKET BASE ASS'Y LH Job Number: 48209B Part Number: D3053041 Job Number: Seq. #: **Machine Or Operation:** Description: 9.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 10.0 QC6 Comment: DIMENSIONAL CHECK 11.0 **Comment: POWDER COATING** START Powder Coat White Gloss (Ref: 4.3.5.2) as per QSI 005 4.3START TIME: 2ND 7:050m OVEN TEMPERATURE: _ FINISH TIME: INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 QC3 Comment: INSPEC POWDER COAT/CHEMICAL CONVERSION 13.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and FINAL INSPECTION/W/O RELEASE 14.0 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Aerospace	Lta
----------------	-----


W/O:			W	ORK ORDER CHANG	SES					***************************************	
Part No:	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Appiovai	
							;				
Part No	•	PAR #:	Fault Cate	gory:	NCR:	Yes N	lo DQA	\:	Date:		
	Re	solution:	Dispositio	n:	QA: N	WC Clos	osed: Date:				
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE	(NCR)					
DATE	STEP	Description of NC			tion B	0' 0	Verific	ation	Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector	




	•									
W/O:			WO	RK ORDER CHANG	ES	· · · · · · · · · · · · · · · · · · ·				
DATE	STEP	PRO	R#: Fault Category: NCR: Yes No DQA: Date: Disposition: QA: N/C Closed: Date: WORK ORDER NON-CONFORMANCE (NCR) f NC Corrective Action Section B	Approval QC Inspector						
								,		
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	A:	Date:		
	Resc	olution:	Disposition	II	_ QA: N/C CI	osed:	·-·	Date:		
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			-	
DATE	STEP	Description of NC	ļ				Verification Appro		vai Approvai	
		Section A				J OCCU	on C	Chief Eng	QC Inspector	
		•								



W/O:			WO	RK ORDER CHANG	GES				
Part No:	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	A :	Date:	
	Resolution: Disposition: QA: N/C Clo				osed:		Date:		
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCF	R)			
DATE	STEP	Description of NC	Initial	Corrective Action Sec Action Description	etion B Sign 8		cation	Approval	Approval
		Section A	Chief Eng	Chief Eng	Date	Secti	ion C	Chief Eng	QC Inspector
•									



	•											
W/O:	/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	:	PAR #:	Fault Categ	Jory:	NCR: Yes	No DQ	A:	Date: _				
	Reso	olution:	Disposition	1:	_ QA: N/C Cld	sed:		Date: _				
NCR:			WORK ORDE	ER NON-CONFORMA	ANCE (NCR)		- // - // -				
DAŢE	STEP	Description of NC Section A	Initial	Corrective Action Section Description	ion B		cation	Approval	Approval			
		Section A	Chief Eng	Chief Eng	Date	Secti	on C	Chief Eng	QC Inspector			
								-				
					And a second sec	:						



W/O:			WORK ORDER C	HANGES				
DATE	STEP	PROCE	DURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	o:	PAR #:	Fault Category:	NCR: Yes	No DQ	A:	Date: _	

Resolution: _____ Disposition: ____ QA: N/C Closed: ____ Date: ____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B			rification Approval					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector				
						!						
								:				
	ate & initial al						:					